



Transformer Repair Report

Customer: Cuba Municipal Utilities***

202 N Smith St
Cuba, MO

65453

Pick up Date: 02/22/24

Load #: 190800

Customer Approval: _____
Date Customer Signature

Please check appropriate column (repair or recycle), sign and return to Solomon Corporation

<u>MFG</u>	<u>Serial #</u>	<u>CO #</u>	<u>Taps</u>	<u>Arrestor</u>	<u>Repair Price</u>	<u>Repair</u>	<u>Replace Price</u>	<u>Replace</u>	<u>Recycle</u>
1ph Padmount									
<i>15.0 KVA (12470GrdY/7200 - 240/120)</i>									
COOP	9938004867	N/A	None		\$1,480.00	<input type="checkbox"/>			<input type="checkbox"/>
			Loop, Wells and Inserts (15 KV (8.3/14.4)), Bayonet fusing, Stud, Mineral Oil, Recondition Unit	Recondition unit Replace the damaged Primary Bushing(s)					
<hr/>									
<i>25.0 KVA (12470GrdY/7200 - 240/120)</i>									
ABC	80B72134	N/A	None		\$1,500.00	<input type="checkbox"/>			<input type="checkbox"/>
			Loop, Dead Feed (200 Amp 15 KV (8.3/14.4)), Bayonet fusing, Stud, PRV, Mineral Oil, Recondition Unit	Recondition unit Replace the damaged Primary Bushing(s) Repair bottom of tank					
<hr/>									
<i>50.0 KVA (12470Y/7200 - 240/120)</i>									
SOL	M05J18487	N/A	None		\$0.00	<input type="checkbox"/>			<input type="checkbox"/>
			Loop, Wells and Inserts (15 KV (8.3/14.4)), Bayonet fusing, Stud, PRV, Mineral Oil, Damaged beyond repair	Unit damaged beyond repair Recommend replacing for \$5,795					
<hr/>									
<i>50.0 KVA (12470Y/7200 - 240/120)</i>									
EDP	J10139411	N/A	None		\$4,718.00	<input type="checkbox"/>			<input type="checkbox"/>
			Loop, Wells and Inserts (15 KV (8.3/14.4)), Bayonet fusing, Stud, PRV, Mineral Oil, Rewind Unit	New Copper Windings Repair Sill, Cabinet, and Tank					

Note:

(1) PCB Oil Test @ 25.00 EA for samples pulled on untested units that were received at Solomon Corporation

Transformer Recondition Repair Price Includes:

36 Month Warranty (materials and workmanship), 1) Initial Testing 2) New Gaskets 3) New Pressure Relief 4) Non-PCB Mineral Oil 5) Pressure Test 6) Final Electrical Testing 7) Sanding & Painting 8) Freight (pick up & delivery)

Transformer Rewind Repair Price Includes:

36 Month Warranty (materials and workmanship), 1) Initial Testing 2) New Gaskets 3) New Pressure Relief 4) Non-PCB Mineral Oil 5) New Primary Windings 6) New Secondary Windings 7) New Insulation 8) Pressure Test 9) Final Electrical Testing 10) Sanding & Painting 11) Freight (pick up & delivery)